## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Group Art Unit: 2782

In re application of

Michael C. Stolowitz

Application No. 09/411,698

Filed:

October 1, 1999

For:

ON-THE-FLY REDUNDANCY OPERATION IN

THE SYNCHRONOUS DISK ARRAY CONTROLLER

Date:

May 19, 2000

Examiner:

Thuan N. Du

## **AMENDMENT**

## TO THE ASSISTANT COMMISSIONER FOR PATENTS:

In response to the March 28, 2000 Office Action, please amend the above-identified patent application as follows.

In the Specification:

At page 1, line 14, after "May 3, 1996" change the period to a comma and add -- now U.S. Pat. No. 6,018,778.--

At page 25, line 27, after "multiplexer" change "920" to --921--.

At page 26, line 2, after "multiplexer" change "920" to --921-- (two occurrences)

At page 26, line 29, after "multiplexer" change "920" to --921--.

At page 27, line 23, after "multiplexer" change "920" to --921--.

In the Drawings:

Proposed changes to Figure 9 are presented in the enclosed red-lined copy.

In the Claims:

Please amend claim 1 as follows:

PortInd2-4254940.1 0044541-00002

1. (Amended) A method of reading striped digital data from a RAID array of disk drives, each drive having a respective data port of predetermined width coupled to an internal buffer, the method comprising the steps of:

37

